

# SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#35

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

NEW YORK \* BROOKLINE  
CHICAGO \* DETROIT

January 1, 1959

Subject: BODY - MODEL A-9

Description: DOOR LOCKS

Door lock operation for locking and unlocking doors can often become a source of trouble, particularly when key holes are exposed to road dust and freezing temperatures.

Lock tumblers should be maintained in operating order by periodic insertion of powdered graphite into the keyhole during P.M. servicing of the car.

By: NEW YORK SERVICE DEPARTMENT