

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#4

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1958

Subject: ELECTRICAL - MODEL A-9

Description: WIRING INSPECTION

Wiring circuits of the car, particularly the under-dash wiring, should be inspected during P.M. Service periods.

All connectors fastened to the various instruments are to be tightened and wires inspected for proper clearance from any metal obstructions.

A suggested method of tightening the connector nuts is through the use of a 3/8" ferret type socket wrench.

Loose connections result in increase of circuit resistance resulting in damaged instruments and gauges.



By: NEW YORK SERVICE DEPARTMENT