

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#28

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1959

Subject: ENGINE - MODEL A-9
Description: ENGINE BLOCK CORROSION

Due to deposits which form in engines, it is recommended that engine block flushing and cleaning operation be considered on a periodic P.M. service. Any restriction in the engine assembly usually affects proper cooling and causes overheating.

For proper maintenance of the cooling system, it is suggested to completely drain and flush out engine blocks. Refill with clean water, using an approved rust inhibitor solution.

This will insure a clean passage throughout the engine and provide for adequate cooling.

By: NEW YORK SERVICE DEPARTMENT