

SERVICE BULLETIN

#14

CAB SERVICE & PARTS CORPORATION

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1959

Subject: STEERING - MODEL A-9
Description: POWER STEERING CONTROL VALVE ADJUSTMENT

REFER TO PAGE 7-6 - PARTS CATALOG (1ST EDITION)

1. Remove power head cap #41.
2. Tighten control valve nut securely on spool bolt, then back off 1/4 turn.
3. Replace cap and tighten (10-15 lb. torque)
4. Tighten all connecting fluid lines.
5. Inspect reservoir tank for proper fluid level.

NOTE: On all inspections of power steering assembly, engine must be running to determine steering direction in power loss.

By: NEW YORK SERVICE DEPARTMENT