

# SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#31

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

NEW YORK \* BROOKLINE  
CHICAGO \* DETROIT

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

January 1, 1959

Subject: TUNE-UP - MODEL A-9

Description: SPARK PLUGS

Whenever replacing spark plugs into engines, it is very important that cylinder head spark plug opening hole threads are thoroughly cleaned of rust and carbon accumulation.

Adjust electrode gap setting to .028.

After installation, plugs should be tightened with a torque wrench applying 40-pound torque.

If spark plugs are not completely tightened, they will operate much hotter than normally and cause premature failure.

By: NEW YORK SERVICE DEPARTMENT