

# SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#34

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

NEW YORK \* BROOKLINE  
CHICAGO \* DETROIT

January 1, 1959

Subject: BODY - MODEL A-9

Description: CLEANING DRAIN HOLES IN DOOR ASSEMBLY

To eliminate the possibility of water accumulation in door assemblies, it is suggested that the 4 drain holes on each door are cleared and cleaned out at least once each month.

These holes are located at the bottom of the doors where the outer panel is joined to the door frame, and are in the shape of a half-moon.

Inserting a screwdriver into holes will clear all road dirt which often restricts draining off water after cars are washed or operating in rainy weather.

By: NEW YORK SERVICE DEPARTMENT