

SERVICE BULLETIN Spec. #120

CAB SERVICE & PARTS CORPORATION
NEW YORK * BROOKLINE
CHICAGO * DETROIT

July 1, 1959

Subject: BRAKES - MODEL A-9
Description: SERVICING OF HYDROVAC ASSEMBLY

IMPORTANT

The operating features of the power brake are entirely dependent on proper functioning of the Hydrovac unit, which is located under the hood at the left front side of the chassis.

Brake application assist through this unit requires that all moving components are free of foreign dust particles. To prevent these foreign materials from entering the Hydrovac unit, there is installed at the forward end a filter unit consisting of a hair material which is held in place by a perforated plate which allows air to enter into the Hydrovac assembly.

The recommended service for assuring proper operation of this unit is as follows, and should be completed on a six month service interval:

1. Remove lock ring holding perforated plate in place.
2. Remove hair filter.
3. Wash filter thoroughly in gasoline or naphtha, and dry by blowing air through the hair filter until there is no solution remaining.
4. Reinstall filter.
5. Install plate and lock ring.

By: NEW YORK SERVICE DEPARTMENT