

# SERVICE BULLETIN

## CAB SERVICE & PARTS CORPORATION

NEW YORK AND CHICAGO

---

SUBSIDIARY OF

**Checker Cab**  
Manufacturing Corporation

March 1, 1956

Subject: DRIVERS COMPARTMENT FLOOR MAT

Description: MODEL A-8

General appearance of the front compartment floor covering can be improved with the application of a rubberized black paint.

After continual washing of floor covering over an extended period the surface of the mat appears hazed and unclean.


It is therefore recommended that a good floor covering paint is applied to improve the appearance of the driver's compartment.

A rubberized paint # EN 19172 manufactured by Egyptian Lacquer is available at Cab Service & Parts Corporation, New York.

By NEW YORK  
SERVICE DEPARTMENT

**SERVICE BULLETIN**  
**CAB SERVICE & PARTS CORPORATION**  
NEW YORK AND CHICAGO

---



March 1, 1956

Subject: PASSENGER COMPARTMENT LEATHER CLEANING

Description: MODEL A-8


In order to properly clean the leather in the Passenger's and Driver's compartments, it is suggested that a mild alkaline cleaner be used.

This cleaner must be of a material that will not affect the nylon threads in the seat or back cushions and after proper cleaning is done, precautions must be taken to see that all cleaning fluid is removed as completely as possible from the interior.

By NEW YORK  
SERVICE DEPARTMENT

**SERVICE BULLETIN**  
**CAB SERVICE & PARTS CORPORATION**  
NEW YORK AND CHICAGO

---



March 1, 1956

Subject: PASSENGER COMPARTMENT LEATHER CLEANING

Description: MODEL A-8

In order to properly clean the leather in the Passenger's and Driver's compartments, it is suggested that a mild alkaline cleaner be used.

This cleaner must be of a material that will not affect the nylon threads in the seat or back cushions and after proper cleaning is done, precautions must be taken to see that all cleaning fluid is removed as completely as possible from the interior.

By NEW YORK  
SERVICE DEPARTMENT