

# SERVICE BULLETIN

## CAB SERVICE & PARTS CORPORATION

#30

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

NEW YORK \* BROOKLINE  
CHICAGO \* DETROIT

January 1, 1959

Subject: EXHAUST SYSTEM - MODEL A-9

Description: MUFFLER INSPECTION

Due to variance in lead deposits and carbon formation, exhaust mufflers are often affected through restrictions of the small holes in the silencing tubes of the muffler, and result in retarding efficient operation of the engine.

It is suggested that mufflers be periodically inspected by tapping with a blunt tool. If a heavy, dull sound is noted, then in all probability, muffler should be replaced. A hollow sound indicates proper operation of muffler unit.

The above preliminary inspection should be completed without removal of the muffler.

By: NEW YORK SERVICE DEPARTMENT