

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

#79

February 11, 1959

Subject: FUEL SYSTEM

Description: CARBURETOR AIR BLEED CHANNEL

During tune-up procedures of the carburetor, it is suggested that particular attention be given to the air bleed channel unit.

Through variation of fuel mixtures, there is a possibility that carbon may accumulate in this channel, which will affect gasoline economy.

The following procedure is suggested:

1. Disconnect gas line at carburetor.
2. Remove 6 screws from top of carburetor.
3. Insert #54 drill into air bleed port and twist by hand to remove carbon accumulation.
4. Blow out with air.
5. Reinstall carburetor top and gas line.

When carbon accumulates at low mileage intervals, investigate choke setting for too lean mixture.

By: NEW YORK SERVICE DEPARTMENT