

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#29

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1959

Subject: ENGINE - MODEL A-9

Description: VALVE MAINTENANCE

Engine valve adjustments or replacement of tappets and valves and springs require periodic inspections for extended performance and maximum efficiency of the engine assembly.

In order to more thoroughly complete this type maintenance, it is suggested that whenever valve maintenance is necessary, the manifold assembly should be removed for access to the valve enclosure.

During this inspection, all carbon deposits should be removed from valve ports, and new gaskets installed, both at manifold to engine and flange locations.

Estimated time of manifold assembly removal and replacement is approximately 25 minutes.

By: NEW YORK SERVICE DEPARTMENT