

# SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#49

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

NEW YORK \* BROOKLINE  
CHICAGO \* DETROIT

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

January 1, 1959

Subject: TRANSMISSION - MODEL A-9

Description: INSPECTION ON CLEANING PARTS OF AUTOMATIC TRANSMISSION

Whenever component parts of the automatic transmission are removed for inspection or repairs, it is suggested to thoroughly wash all parts in an alcohol solution, such as SALVASOL.

Assemblies such as valve body, pistons and brake band cylinders, require absolute cleansing before replacement into the transmission.

Gasoline or caustic solutions are not recommended, as these solutions will deteriorate seals and result in fluid seepage.

By: NEW YORK SERVICE DEPARTMENT