

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#52

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1959

Subject: TRANSMISSION (AUTOMATIC) - MODEL A-9
Description: MOUNTING CONVERTER TO DRIVE PLATE

When replacing the transmission converter or converter drive plate, the recommended procedure is to tighten the drive plate to converter bolts after the transmission has been installed. This procedure will have a definite effect on prolonging the service life of the drive plate.

It is further recommended that, on PM service inspection, all 6 bolts which mount the drive plate should be loosened and retightened, using a torque limiting wrench to 35 ft. lbs. Access to these mounting bolts can be made by removing the lower cover on the front side of the converter housing.

By: NEW YORK SERVICE DEPARTMENT