

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#50

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1959

Subject: TRANSMISSION - MODEL A-9

Description: TOWING INSTRUCTION FOR AUTOMATIC TRANSMISSION

1. When towing is necessary, place the selector lever in the "N" position and be sure the ignition is turned off.
2. Car should not be towed in excess of 25 M.P.H.

I M P O R T A N T

WHEN TOWING CAR BECAUSE OF TRANSMISSION FAILURE, THE REAR PROPELLER SHAFT MUST BE REMOVED OR DISCONNECTED TO PREVENT DAMAGE TO THE TRANSMISSION.

By: NEW YORK SERVICE DEPARTMENT