

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

99

March 31, 1959

March 31, 1959

Subject: TRANSMISSION (AUTOMATIC)

Description: SHIFT SEQUENCE INSPECTION

Subject: TRANSMISSION (AUTOMATIC)

Description: FLUID LEAKS

Whenever repairs or adjustments are completed to the transmission, it is very important to remove the small breather unit on the transmission and thoroughly clean with a solvent and air pressure, all accumulation of road dirt.

This breather unit is located on the upper right hand corner of the transmission case, above the fluid cooler lines, and may be removed either on or off the car with a 7/16" open end wrench.

Restriction in this breather will often create a back pressure in the transmission and result in unusual fluid seepage around gasket and seal areas.

BY: NEW YORK SERVICE DEPARTMENT

BY: NEW YORK SERVICE DEPARTMENT