

January 28, 1963

ENGINEERING MEMORANDUM #34

TO: J. Stout, P. Visser, R.G. Fuller, J. Coleman, S. Hori, E. Horrigan
K. Luke, F. Leamy (3), R. McCulfor, R. Smith, C. Cornwell,
E. Nelson, J. Copeland, T. Bedard, J. Temple (4), K. Bothe,
L. Hilsky (4), A. Radke (3), D. Markin, B. Herrington (8),
W. Asselin, D. Bach, F. Baldwin, A. Goedhart, S. Megyesi.

FROM: S. Wilson

SUBJECT: CONTROL PLATES - INSTRUMENT PANEL

To eliminate the breakage of Control Plates, the plastic plates will be replaced by a thin aluminum plate.

PARTS TO BE CANCELLED

640252 Plate - Fresh Air Control
640217 Plate - Heater Control
640633 Plate - Air Cond. Control - Spec.
640296 Plate - Fresh Air Control RH

ENGINEERING CHANGES REQ'D.

639318 Switch Assem. - Rotary (Chg. B.)
120395 Washer - 15/32 I.D. x 59/64 O.D. (Temp. extra
one for A-12 Models & one extra Air Cond.)

NEW PARTS REQ'D.

640466 Plate - Fresh Air Control
640463 Plate - Heater Control
640465 Plate - Air Cond. Control
640464 Plate - Fresh Air Control RH

This revision is to be effective when balanced stock of old is depleted. As there is a difference in appearance it will be necessary to use either all plastic or all aluminum plates on each particular vehicle.

* Note:

640463 Incorporated on Chassis #12520 A-12,A-12W,A-12E (Aerobus #760)
**640464 Incorporated on Chassis #12731 A-12,A-12W,A-12E (Aerobus #799)
640465 Incorporated on Chassis #12520 A-12,A-12W,A-12E (Aerobus #760)
**640466 Incorporated on Chassis #12731 A-12,A-12W,A-12E (Aerobus #799)

*Note Added 10-14-63;
**Aerobus #799 Added 10-28-63;