

March 4, 1964

ENGINEERING MEMORANDUM #49

TO: J. Stout, P. Visser, R. Fuller, J. Coleman, S. Hori,  
E. Horrigan, K. Luke, F. Leamy (3), R. McCulfor,  
R. Smith, C. Cornwell, E. Nelson, J. Copeland, T. Bedard,  
J. Temple (4), K. Bothe, L. Hilsky (4), A. Radke (3),  
D. Markin, B. Herrington (8), W. Asselin, D. Bach,  
F. Baldwin, A. Goedhart, S. Megyesi.

FROM: S. Wilson

SUBJECT: HEATER TEMPERATURE CONTROL REVISIONS

Due to the greater travel required to operate the new temperature control valve the controls for all except Taxicab will be changed to a push-pull type. The Taxicab control will remain the same with revisions as listed below.

A. TAXICAB PARTS AFFECTED

<u>OLD NO.</u>	<u>DESCRIPTION</u>	<u>NEW NO.</u>
634094	Lever - Heater Control	640565
633908	Cable Assem. - Temp. Control	641555
633061	Control Assem. - Heater	641556
633903	Control Assem. - Fresh Air (Revise)	Same No.

B. PASSENGER CAR & STATION WAGON PARTS AFFECTED

<u>OLD NO.</u>	<u>DESCRIPTION</u>	<u>NEW NO.</u>
640220	Lever - Heater Control (Reduce qty. by 1)	Same
640221	Spacer - Heater Control (Reduce qty. by 2)	Same
626420	Retainer - Tinnerman (Reduce qty. by 2)	Same
640212	Connector - Heater Control (Reduce qty. by 1)	Same
626547	Clip - Tubular (Reduce qty. by 1)	Same
640022	Knob - Heater Control (Remove Heater Usage)	Same
626537	Screw - #10-32 x 5/8 (Reduce qty. by 1)	Same
626441	Nut - #10 Hex. Lock (Reduce qty. by 1)	Same
640275	Spacer (Add 1 for Heater)	Same
640223	Panel - Instr. Center (Revise Hole)	Same
633908	Cable Assem. - Temp. Control	641540
640463	Plate - Heater Control	642504
92668	Knob (Increase by 1)	Same
639225	Control Assem. - Heater	641557

C. AEROBUS PARTS AFFECTED

Same as Passenger Car except:

<u>OLD. NO.</u>	<u>DESCRIPTION</u>	<u>NEW NO.</u>
639818	Cable Assem. - Heater Temp.	639844
640611	Panel - Instr. Center (Revise Hole)	Same

Taxicab, Passenger Car & Station Wagon Changes will be incorporated with new engines.

Aerobus is to be incorporated as soon as parts are available.