

March 9, 1964

ENGINEERING MEMO #51

TO: J. Stout, P. Visser, R.G. Fuller, J. Coleman, S. Hori, E. Horrigan
K. Luke, F. Leamy (3), R. McCulfor, R. Smith, C. Cornwell, E. Nelson,
J. Copeland, T. Bedard, J. Temple (4), K. Bothe, L. Hilsky (4),
A. Radke (3), D. Markin, B. Herrington (8), W. Asselin, D. Bach,
F. Baldwin, A. Goedhart, S. Megyesi.

FROM: S. Wilson

SUBJECT: TIRE DOOR LATCH (A-12W)

A. NEW PARTS REQ'D

640759 Latch - Tire Door
640761 Spring- Tire Door Latch
640758 Retainer - Tire Door Latch
639901 Latch Assem.-Tire Door
639884 Panel Assem.-Tire Door and Latch
640776 Reinf. - Tire Door - Rear
640760 Pin - Tire Door Latch

B. CHANGES REQ'D

636446 Support - Rear Floor (Hole & Flange Added)
635180 Support Assem.-Rear Floor (Hole Added Per Detail)
635168 Panel Assem.-Tire Door (Hole Added Per Detail)
103361 Cotter Pin - 1/16 X 1/2 (Incr. usage by 1)
161895 Screw - #10 X 1/2 Tapp (Incr. usage by 2)
138479 L/Washer - #10 (Incr. usage by 2)

This revision is to be effective as soon as all parts are available.

* This revision incorporated on Chassis No. 22308

* Note Added 7-7-64;