

October 26, 1964

ENGINEERING MEMORANDUM #75

TO: J. Stout, R. Fuller, S. Wilson, S. Hori, E. Horrigan, K. Luke, F. Leamy(3)
R. McCulfor, A. Radke(3) W. Asselin, R. Smith, A. Goedhart, E. Nelson
C. Cornwell, S. Megyesi, B. Herrington(8) R. Bach, D. Markin, B. Baldwin
J. Copeland, J. Coleman, T. Bedard, K. Bothe, L. Hilsky(4) J. Temple(4),
B. Lewis

FROM: S. Wilson

SUBJECT: CARD CASE REVISION TO MEET NEW YORK CITY SPECIFICATIONS

The complete assemblies (633346 & 643158) are interchangeable for service but the individual parts are not interchangeable.

The new assemblies must be incorporated in New York City Cabs as soon as possible and the balance of the balanced old stock used for service or production cabs other than for New York.

The new York City Cab specifications require two #57 bulbs (2c.p. over each card.) The following changes are required to meet these specifications:

OLD PART NO.	NAME	NEW PART NO.
633346	Card Case Assem. - Glove Compt.	643158
634537	Panel Glove Compt. Card Case	640395
634394	Shield - Glove Compt. Card Case Lamp	640546
633140	Socket Assem. - Courtesy	
	Socket Harness Assem. - Card Case Light	641299
142450	Bulb 4 c.p. 12/16 Volt Single Contact (1)	
	Bulb 2 c.p. Single Contact Mfg. #57 (2)	127934
631161	Installation - Glove Compt. Card Case (Ref. Drawing)	637364-A

This Revision incorporated on Chassis No. 28124 plus some earlier numbers when specifically specified on Prod. Orders.

Chassis No. Added 3-5-65
Chassis No. Revised 7-9-65